

# Maintenance Portfolio

British Maintenance promise to estate agencies:

We cover all property maintenance and building jobs

In-house vetted and qualified operatives

No job is too big or too small, we accept all jobs

We offer fast customer service and fast job reports

Pay us within 28 days

We give you a guaranteed one-year warranty

Don't take our word for it, see some of our jobs in pages below



### Apollo Drive, Wellingborough, Northamptonshire



New bath plug removed from sealed



New outside stop valve



New bath plug

### Calwell Drive, Maidenhead



Crack on roof before repair work



During roof work



Repaired roof & reapplied roof tar

























### Ground floor flat, Castle Road, London



New bath panel



New bathtub & new tiles installed

### Cavendish Mews, Heene Place, Worthing



Rusty old radiator



Old & new radiators



New radiator

























### Claygate Hare Lane, Esher, Surrey



Old cartridge removed



Installed new cartridge



Testing new system

### Coventry Road, Rugby, Warwickshire



Old snapped overflow pipe



The overflow pipe being installed



New cold-water tank overflow pipe installed


























### Hinkler Road, Southampton







Installed new Full Bathroom



Installed new carpet & new PVC window

#### Joyce Silver Court, Addington Road, Wellingborough



Adjusted & repaired the PVC window



New door lock installed



New mixer tap installed

























### Kingfisher Drive, Maidenhead, Windsor



Testing boiler PCB

#### Longfellow Road, Worcester Park, London



Installed new bath, tiling and sealed



New shower mixer tap



Full repointing of the roof

























#### Matthias Court, Church Road, Richmond



New sink trap & waste connectors



New earth bonding & WM inlet hose



New under sink waste trap installed

#### Midleton Road, New Malden



Installed new condensing pipe



New boiler condensing trap installed

























#### Oaks Cottage, George Street, Wellingborough



Damaged PVC door lock



Installed new PVC door lock



Restoring old solid wooden door

#### Palace Road, London



New door lock installed



Slide door adjusted & tested



Installed new wardrobe shelve


























### Savoy Close, Birmingham



Dust sheet installed before painting



Newly painted bedroom

#### Smallwood Road, London



Old fence



New fence installed



Garden left clean after fence installed

























#### Southolm Street, Southwest, London



New PVC window installed



New mixer taps installed



New bath screen installed

#### Tithelands, Harlow, Essex



Installed new PRV valve



Tested boiler after refilling system

























#### Wilton Court, Westmount Close, London



Old boiler before replacement



Installed new boiler

### Woodland Rise, London



Installed 50cm wide fridge, with new power point



Our operatives in full PPE & mask

























## Kings Road, Sudbury, Suffolk




Supplied & installed new range cooker

#### Middleton Way, Crawley, West Sussex



New shower handle railing installed



Shower thermostatic valve repaired

























#### Ennerdale Close, Sutton, London



New integrated freezer



Testing new fridge working

# Ardmore Lane, Buckhurst Hill, Essex



New electric hob installed

# Brolly Works, Allison Street, Birmingham



Installed new sink & mixer tap



























### Chancellor's Road, London



Installed new bath mixer taps

Fullers Mead, Harlow, Essex



New fire door installed

George Street, Rushden, Northamptonshire



Installed a new shower

























Sheppeys, Haywards Heath, West Sussex Pavior Road, Nottingham



New fence installed



New shower room door & rubber installed

Lancaster Ave, Mitcham, Greater London



New fire door installed

Rawnsley Drive, Kenilworth, Warwickshire



New garage door installed



























#### Meridian Court, Fernleigh Close, Croydon



Replacing bath overflow waste pip



New trap installed

#### Cambie Crescent, Colchester



Supplied & installed new oven

# Mill Green, Congleton, Cheshire



Supplied & installed new toilet & lino flooring

























### Dale Lodge, Shepherds Hill, Highgate



Painted living room after repairs to walls

#### Turpin Close, Gainsborough, Lincolnshire



Upgrade gas meter outlet pipework from 15mm to 22mm

#### Boundary Close, Doncaster



Installed new window



























#### Barley Ponds Road, Ware, Hertfordshire



Gardening work



Repaired entrance wall

### Bartok Close, Basingstoke



Repair to TV aerial

### Broadfield Road, London



Installed new window rubber and window hinge

























### Admiral Way, Hyde, Greater Manchester



Isolation switch replaced



Old faulty electrical shower



New electrical shower installed

#### Aria House, London



Adjusted & repaired fallen wardrobe



Floor installation

























### Birley Road, London



Installation of new shower cartridge



New shower controls

#### Barnmead, Haywards Heath, West Sussex



Old element being removed



New cylinder heating element installed



























## Caernarvon Crescent, Milton Keynes



Chimney pointed & new lead flashing



New ceiling following painting



Porch roof skimmed

### Brackenbury Gardens, London



Sealed shower room



Installed new bannister



























#### Capitol Square, Surrey



Pipework boxing (before)



Pipework boxing (after)

Church Hill Road, Surbiton

City House, London



Installation of a new expansion vessel



Changing toilet parts



























#### Carlington House, Normanton Road, London



New bathtub toilet & sink installed



New tiles installed



Replacing pipework inside boxing

### Eastbourne Road, London



Installed bathtub waste pipes



Installed new compression boiler valves



























### Garrick Close, London



Old water filter



New water filter installed

# Flaxley Close, Lincoln, Lincolnshire



New vented MEGAFLO cylinder installed

Fraser House, Clapham, London



New trap installed under bathtub

























### Kelvin Gardens, Croydon



Applied silicon around bathtub



Grouted all bathroom tiles

### Eggleton Drive, Wellingborough, Hertfordshire



New alternators installed



New carpet fitted



New pump motor installed

























#### Garth Road, Morden, London



Old boiler before installation



New boiler being commissioned



Flue test on new boiler

### Granville Chambers, Wellingborough



New toilet installation



New grouts on tiles
























ksmiths Residen



### Kettering Road, Kettering, Northamptonshire



Cleaning drains following removal waste



Replaced soil down water pipe



Sealed with cement newly installed soil pipe

### Kempsford Gardens, London



Damage caused by another contractor



New tiles installed, grouted & made good

























#### Lapwing Court, Wesham, Preston



Old expansion vessel removed



New expansion vessel installed



New pump fitted

#### Mildenhall Road, Birmingham, West Midlands



Damage in underground waste pipe system



Unblocked manhole & tested water running



Inspected all the manholes around the property

























### Levy Close, Andover, Hampshire



Damaged tiles replaced



New lead flashing installed

### London Road, Redhill, Surrey



Sealed full roof hips

### Malthus Path, London



New toilet installed



























#### Melville Court, London



Repair to leaking joints under bath



Testing leak for soundness

Newton Street, Covent Gardens, London

Nina Carroll Way, Kettering, Northamptonshire



Installed a new washing machine



Washer & Dryer being installed

























### Ordinance Way, Ashford, Kent



Old boiler before installation



New boiler being tested



New room stat installed

### New Street, Wellingborough



Installed new Ideal boiler



New boiler being tested during installation



























### Pied Bull Court, London



New kitchen installed



New bathroom, tiling & flooring installed



New shower installed

### Perie Brook, Stafford



Installation of vinyl floor (before)



Installation of vinyl floor (after)



























### Saint John's Way



Damaged ceiling



Operative cleaning up after work

### Plessey Road, Northumberland



Damaged toilet handle



New toilet handle

























### Putney Hill, London



Replacing toilet flusher



New flusher to fit into the toilet basin

### Ragsdale Street, Kettering



Sink blocked (before work)



Unblocked sink

























### Ross Road, Wallington, Greater London



Replacing shower valves



Tidy job, tiles were not damaged

#### Rosebery Ave, Malden, London



New flexi hose & earth bonding installed



























### Springfield Road, Luton



Covering carpets to prevent damage



New sink & toilet installed



New ceiling installed

#### Summerville Terrace, London



New oven fan & heating element installed



Oven left working following parts replacement

























Site Drainage Refurbishme



#### Tranmere Road, London



Installed new boiler harness



Testing boiler for safety following the work

# Sutcliffe Drive, Leamington Spa, Warwickshire



Roofing sheets installed

### Trehurst Ave, Birmingham



New boiler installed

























### Warwick Road, London



Old mixer taps



New mixer taps installed

### Woodcote Road, Wallington, London



New shower installed



New shower tested working



























### Washington Square, Kettering, Northamptonshire



New waste pipe installed



New mixer taps following replacement



Chemicals added to central heating system

### Welsh Road, West Southam



Installation of new gutters





















